

TABLE 2
PREVIOUSLY IDENTIFIED ASBESTOS CONTAINING MATERIALS
BALDWIN HARDWARE MANUFACTURING CORP.
READING, PENNSYLVANIA

Asbestos Containing Material	Inspection Info.		Sample No.	Sample Location		Asbestos Content	Est. Quantity (If Provided)	
	Company	Date		Building	Area Description			
Black Fittings	EOG	1/29/2001	Assumed	Office Building	3rd floor above ceiling of President's and Secretary's offices	22% Chrysotile	4	#
White Fittings	EOG	1/29/2001	BHAB-3-F01	Office Building	3rd floor above ceiling of President's Office	2% Chrysotile 3% Amosite	11	#
White Fittings	EOG	1/29/2001	BHAB-3-F01	Office Building	3rd floor behind walls and ceilings of President's & Secretary's offices	2% Chrysotile 3% Amosite	12	#
Pipe Fitting Debris	EOG	1/29/2001	BHAB-3-F02	Office Building	3rd floor above ceiling of President's office	2% Chrysotile 3% Amosite	30	SF
Spackle and Tape - layer 1	EOG	1/29/2001	BHAB-3-DWT01-06 L01	Office Building	3rd floor interior wall separating President's and Secretary's office	3% Chrysotile	12	SF
Spackle and Tape - layer 3	EOG	1/29/2001	BHAB-3-DWT01-06 L03	Office Building	3rd floor wall between President's and /Secretary office	2.75% Chrysotile	12	SF
Linoleum	EOG	1/29/2001	Assumed	Office Building	2nd floor Mail Room	30% Chrysotile	600	SF
Black Fittings	EOG	1/29/2001	Assumed	Office Building	2nd floor above ceilings	22% Chrysotile	22	#
Black Fittings	EOG	1/29/2001	Assumed	Office Building	2nd floor inaccessible spaces	22 % Chrysotile	25	#
White Fittings	EOG	1/29/2001	BHAB-3-F01	Office Building	2nd floor behind walls and ceilings	2% Chrysotile 3% Amosite	366	#
White Fittings	EOG	1/29/2001	BHAB-3-F01	Office Building	2nd floor inaccessible spaces	2% Chrysotile 3% Amosite	25	#
Linoleum	EOG	1/29/2001	Assumed	Office Building	1st floor First Aid Room	25% Chrysotile	200	SF
Floor tile beneath non-asbestos tile	EOG	1/29/2001	Assumed	Office Building	1st Floor Lunch Room/Café	2% Chrysotile	720	SF
Black Fittings	EOG	1/29/2001	Assumed	Office Building	1st floor above ceiling of Men's Bathroom and Lunch Room	22% Chrysotile	39	#
Black Fittings	EOG	1/29/2001	Assumed	Office Building	Above Women's Bathroom Ceiling/Inaccessible chases	22% Chrysotile	10	#
White Fittings	EOG	1/29/2001	BHAB-1-F02	Office Building	1st floor mechanical portion of Parts Department.	40% Chrysotile	153	#
White Fittings	EOG	1/29/2001	BHAB-1-F02	Office Building	1st floor ceilings above Men's Bathroom & Lunch Room	40% Chrysotile	57	#
White Fittings	EOG	1/29/2001	BHAB-1-F02	Office Building	1st floor in ceilings above Women's Bathroom and inaccessible chases	40% Chrysotile	40	#
Elbow - Thermal	K&A	2/22/1996	Bald-2-8-013	3	Polishing Dept.	85% Chrysotile	N/A	N/A
Elbow - Thermal	K&A	2/22/1996	Bald-2-8-014	3	Polishing Dept.	85% Chrysotile	N/A	N/A
Elbow - Thermal	K&A	2/22/1996	Bald-2-8-015	3	Polishing Dept.	80% Chrysotile	N/A	N/A
Elbow - Thermal	K&A	2/22/1996	Bald-2-8-017	2	Forging Dept.	3% Chrysotile	N/A	N/A
Elbow - Thermal	K&A	2/22/1996	Bald-2-8-018	1	Door Pull Cell Dept.	90% Chrysotile	N/A	N/A
Tee - Thermal	K&A	2/22/1996	Bald-2-8-019	1	Escutcheon Plate Cell	80% Chrysotile	N/A	N/A

Notes:

EOG - Environmental Options Group

KEOG 2001 - Karl Associates

Assumed - Determined to be ACM based on previous inspection

SF - Square feet

LF - Linear feet

TABLE 2
PREVIOUSLY IDENTIFIED ASBESTOS CONTAINING MATERIALS
BALDWIN HARDWARE MANUFACTURING CORP.
READING, PENNSYLVANIA

Asbestos Containing Material	Inspection Info.		Sample No.	Sample Location		Asbestos Content	Est. Quantity (If Provided)	
	Company	Date		Building	Area Description			
Elbow - Thermal	K&A	2/22/1996	Bald-2-8-023	4	Contract Hardware	80% Chrysotile	N/A	N/A
Tee - Thermal	K&A	2/22/1996	Bald-2-8-024	4	Contract Hardware	80% Chrysotile	N/A	N/A
Elbow - Thermal	K&A	2/22/1996	Bald-2-8-026	2	Forging Dept. Lunch Area	80% Chrysotile	N/A	N/A
Elbow - Thermal	K&A	2/22/1996	Bald-2-8-027	2	Forging Dept. Lunch Area	80% Chrysotile	N/A	N/A
Tee - Thermal	K&A	2/22/1996	Bald-2-8-028	2	Forging Dept. Lunch Area	80% Chrysotile	N/A	N/A
Elbow - Thermal	K&A	2/22/1996	Bald-2-8-030	7	Machine Shop	90% Chrysotile	N/A	N/A
Elbow - Thermal	K&A	2/22/1996	Bald-2-8-032	7	Machine Shop	85% Chrysotile	N/A	N/A
Floor Tile-2nd Layer	K&A	2/22/1996	Bald-2-8-038	7	Machine Shop, Lunch Room	2% Chrysotile	N/A	N/A
Valve - Thermal	K&A	2/22/1996	Bald-2-8-042	8	Receiving Area	85% Chrysotile	N/A	N/A
Aircell Pipe Insulation	K&A	2/22/1996	Bald-2-8-043	8	Receiving Area	15% Chrysotile	N/A	N/A
Tee - Thermal	K&A	2/22/1996	Bald-2-8-048	9	Plating Dept	2% Chrysotile	N/A	N/A
Elbow - Thermal	K&A	2/22/1996	Bald-2-8-049	9	Old Lacquer Room	80% Chrysotile	N/A	N/A
Elbow - Thermal	K&A	2/22/1996	Bald-2-8-051	9	Plating Dept	80% Chrysotile	N/A	N/A
Floor Tile-2nd Layer	K&A	2/22/1996	Bald-2-8-054	Office Building	Purchasing Office, Men's Bathroom	3% Chrysotile	N/A	N/A
9 x 9 Floor Tile	K&A	2/22/1996	Bald-2-9-066	50	HVAC Room, Pack. & Assembly	10% Chrysotile	N/A	N/A
Mastic	K&A	2/22/1996	Bald-2-9-067	50	HVAC Room, Pack. & Assembly	20% Chrysotile	N/A	N/A
Mastic	K&A	2/22/1996	Bald-2-9-069	50	Pack. & Assembly, next to offices	15% Chrysotile	N/A	N/A
9 x 9 Floor Tile	K&A	2/22/1996	Bald-2-9-070	50	Pack. & Assembly, offices/entrance	2% Chrysotile	N/A	N/A
Mastic	K&A	2/22/1996	Bald-2-9-071	50	Pack. & Assembly, offices/entrance	15% Chrysotile	N/A	N/A
9 x 9 Floor Tile	K&A	2/22/1996	Bald-2-9-075	50	Pack. & Assembly	3% Chrysotile	N/A	N/A
Linoleum	K&A	2/22/1996	Bald-2-9-082	Office Building	First Aid Room	25% Chrysotile	N/A	N/A
Black Elbow	K&A	2/22/1996	Bald-2-12-092	Office Building	Main Offices. 2nd Floor	22% Chrysotile	N/A	N/A
Linoleum	K&A	2/22/1996	Bald-2-12-094	Office Building	Mail Room. 2nd Floor	30% Chrysotile	N/A	N/A

Notes:

EOG - Environmental Options Group

KEOG 2001 - Karl Associates

Assumed - Determined to be ACM based on previous inspection

SF - Square feet

LF - Linear feet